

## **Versión 1.14**

- Se añade compatibilidad con el mando de Daikin BRC1E53.
- Corrección de incidencias menores.

## **Versión 2.0**

- Se desvincula el error externo 99 de errores internos para evitar envíos innecesarios al bus.
- Se resetea el contador interno cada vez que se reciben tramas válidas con el fin de evitar el envío de falsos errores internos.

## **Versión 2.1**

- Corrección de una incidencia: errores de visualización trabajando con ETS4.

## **Versión 2.2**

- Corrección de una incidencia: la versión del dispositivo no coincide con la versión diseñada en ETS.

## **Versión 2.3**

- Se añade compatibilidad con el mando de Daikin BRC1H519W.
- Modificación en los valores de estados de ventilación para que cumplan con el estándar KNX.

## **Versión 2.4**

- Corregida incompatibilidad en modo maestro con algunas unidades.

## **Version 1.14**

- Compatibility with Daikin BRC1E53 remote controller added.
- Minor bug fixes.

## **Version 2.0**

- External error 99 unlink in order to avoid unnecessary sendings.
- Internal counter reset after receiving valid frames in order to avoid sendings of false internal errors.

## **Version 2.1**

- Bug fix: Display errors on ETS4.

## **Version 2.2**

- Bug fix: Device version and ETS version don't match.

## **Version 2.3**

- Compatibility with Daikin BRC1H519W remote controller added.
- Fan status values modification in order to meet KNX standar.

## **Version 2.4**

- Fixed incompatibility with some units in master mode.