

KLIC-DI VRV

Versión 1.8

- Se añade compatibilidad con el mando de Daikin BRC1E53.
- Corrección de incidencias menores.

Versión 1.10

- Se desvincula el error externo 99 de errores internos para evitar envíos innecesarios al bus.
- Se resetea el contador interno cada vez que se reciben tramas válidas con el fin de evitar el envío de falsos errores internos.

Versión 1.11

- Corrección de una incidencia: errores de visualización trabajando con ETS4.

Versión 1.12

- Corrección de una incidencia: la versión del dispositivo no coincide con la versión diseñada en ETS.

Versión 1.13

- Se añade compatibilidad con el mando de Daikin BRC1H519W.
- Modificación en los valores de estados de ventilación para que cumplan con el estándar KNX.

Versión 1.14

- Corregida incompatibilidad en modo maestro con algunas unidades.

Version 1.8

- Compatibility with Daikin BRC1E53 remote controller added.
- Minor bug fixes.

Version 1.10

- External error 99 unlink in order to avoid unnecessary sendings.
- Internal counter reset after receiving valid frames in order to avoid sendings of false internal errors.

Version 1.11

- Bug fix: Display errors on ETS4.

Version 1.12

- Bug fix: Device version and ETS version don't match.

Version 1.13

- Compatibility with Daikin BRC1H519W remote controller added.
- Fan status values modification in order to meet KNX standar.

Version 1.14

- Fixed incompatibility with some units in master mode.